

APPENDIX C

Photo Log



Photo 1 View east from WQ-01 sample site, located within the Reference Wetland. Photo taken on May 29, 2019.



Photo 2 View west from WQ-01 sample site, located within the Reference Wetland. Photo taken on May 29, 2019.



Photo 4 View north from WQ-01 sample site, located within the Reference Wetland. Photo taken during spring sampling on May 29, 2019.



Photo 5 View south from WQ-01 sample site, located within the Reference Wetland. Photo taken during spring sampling on May 29, 2019.



Photo 7 View east from WQ-01 sample site, located within the Reference Wetland. Photo taken during fall sampling on October 16, 2019.



Photo 8 View west from WQ-01 sample site, located within the Reference Wetland. Photo taken during fall sampling on October 16, 2019.



Photo 9 View north from WQ-01 sample site, located within the Reference Wetland. Photo taken on October 16, 2019.




Photo 10 View south from WQ-01 sample site, located within the Reference Wetland. Photo taken on October 16, 2019.



Photo 11 View east from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 12 View west from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 13 View north from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 14 View south from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 15 View east from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 16 View west from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 17 View north from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 18 View southwest from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 19 View east from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 20 View west from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 21 View north from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 22 View south from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 29, 2019.



Photo 23 View east from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 24 View west from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 25 View north from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 26 View south from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 16, 2019.



Photo 27 View south from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 28 View north from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 29 View of the ground of the WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 30 View southeast from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 31 View south from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on October 16, 2019.



Photo 32 View north from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on October 16, 2019.



Photo 33 View east from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 16, 2019.



Photo 34 View west from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 16, 2019.



Photo 35 View southwest from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 36 View southeast from WQ-05b sample site at the previous location of sample site WQ-5c, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 37 View northwest from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 38 View northeast from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 39 View southwest from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 16, 2019.



Photo 40 View southeast from WQ-05b sample site at the previous location of sample site WQ-5c, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 16, 2019.



Photo 41 View south from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 16, 2019.



Photo 42 View north from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 16, 2019.



Photo 43 View east from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 44 View north from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 45 View of the ground conditions at the WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 46 View of the ground conditions at the WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 29, 2019.



Photo 47 View west of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 48 View east of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 49 View north of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 50 View of the ground conditions at the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 29, 2019.



Photo 51 View upstream (southwest) of the FL-01 inflow site. Photo taken during spring sampling on May 29, 2019.



Photo 52 View southeast of the FL-01 inflow site. Photo taken during spring sampling on May 29, 2019.



Photo 53 View upstream (southwest) of the FL-01 inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 54 View downstream (northeast) of the FL-01 inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 55 View upstream (south) of the FL-02 Inflow site. Photo taken during spring sampling on May 29, 2019.



Photo 56 View of the ground conditions at the FL-02 Inflow site. Photo taken during spring sampling on May 29, 2019.



Photo 57 View upstream (south) of the FL-02 Inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 58 View of the ground conditions at the FL-02 Inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 59 View downstream (southwest) of the FL-03 Inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 60 View upstream (southwest) of the FL-03 Inflow site. Photo taken during fall sampling on October 16, 2019.



Photo 61 View southwest of the FL-04 outflow site. Photo taken during spring sampling on May 29, 2019.



Photo 62 View east of the FL-04 outflow site. Photo taken during spring sampling on May 29, 2019.



Photo 63 View southwest of the FL-04 outflow site. Photo taken during fall sampling on October 16, 2019.



Photo 64 View of ground conditions at the FL-04 outflow site. Photo taken during fall sampling on October 16, 2019.